

Work Order ID 77480

77480

Page 1

Thursday, February 02, 2012 1:34:55 PM

Item ID: D206-559-023

Accept

N900040100

Setup Start ***NS1***

Revision ID:

Item Name: Bearpaw

Stop ***NS2***

Start Date: 12/8/2011 Start Qty: 1.00 ***1***

Cust Item ID:

Required Date: 12/9/2011 Req'd Qty: 1.00 ***1***

Customer: CU-DAR001

Reference: RMA RA111297 - RETURN

Approvals: Process Plan: *MF* Date: *12-02-02* Tooling:

Run Start ***NR1***

QC: Date: SPC (Y/N):

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
IIN-D206-559	rev L								

100 0.00

100

QC

Quality Control

Memo

INSPECT RA 111297
D206-559-023 B62036

KIT IS COMPLETE

ADD NEW LABELS AND PAPERWORK

CH6007 *Silva*

0.00

0.00

110

110

Packaging

Packaging

Memo

ID AND STOCK UNDER NEW BATCH NUMBER

0.00

CH6007

CH6007

Work Order ID 77480***77480***

Page 2

Thursday, February 02, 2012 1:34:55 PM

Item ID: D206-559-023

Accept

N900040100Setup Start ***NS1***

Revision ID:

Item Name: Bearpaw

Stop ***NS2***

Start Date: 12/8/2011 Start Qty: 1.00

1

Cust Item ID:

Required Date: 12/9/2011 Req'd Qty: 1.00

1

Customer: CU-DAR001

Reference: RMA RA111297

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start ***NR1***

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop ***NR2***Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
---------	--------	-----------	------------	------------	---------------	-------------

120

QC21- Final Inspection - Work Order Release

0.00

120

QC

Memo

0.00

Quality Control

M.L.J. 12/02/06 *[Signature]*
MF
12-02-06

RA111297

Received @ Dart December 1st, 2011
Inspected @ Dart December 7th, 2011

Instructions for RA 111 297 D407-649-011 B68792 CHG001

- Kit is complete
- Needs new labels and paper work
- Needs new Work Order to go back into stock
- Needs to go back into stock under new BARCH #

Instructions for RA 111 297 D206-559-023 B62036 CHG007

- Kit is complete
- Needs new labels and paper work
- Needs new Work Order to go back into stock
- Needs to go back into stock under new BARCH #